

# *Using the 34401A Multimeter*



**The University of Texas at Arlington  
Electrical Engineering Department  
Electric Circuit Lab I**

In order to measure **resistance**, **DC and AC voltage** and **current**, as well as **frequency** *we* will use the 34401A digital multimeter (DMM).

The 34401A has a built-in microprocessor, *memory* and other electronics components that give it numerous features such as built-in **math** functions, recording and storing up to 512 readings, giving the *maximum*, *minimum* and *average* of the readings.

# 34401A Multimeter

- **6 1/2 digit**, high performance digital multimeter
- AC/DC **voltage** measurements
- AC/DC **current** measurements
- 2 and 4 wire **resistance** measurements
- **Frequency** and Period measurements
- **Math** functions

For **resistance** measurements, one connects the DMM over the resistor.

Notice that for **voltage** measurements one puts the multimeter in *parallel* with the circuit element so that one measures the voltage *across* the element.

In case of a **current** measurement, one must put the DMM in *series* with the element in order to measure the current *through* the element. That involves breaking the circuit in order to insert the multimeter in the circuit loop.

In the following we will discuss the use of the DMM in more detail for resistance, voltage and current measurements.

# Protect Instrument

- 1) Inductive Devices (e.g. transformers, chokes/inductors) induce very high transient voltages.
- 2) Measuring resistance: Avoid contacting probes with live circuits when in resistance modes.
- 3) Measuring Current: Do not connect probes across voltage source.




# Starting Multimeter

- To perform a complete **self-test**, hold down the **shift** key for more than five seconds as you turn on the multimeter.
- *The display will indicate whether test passed. Error messages will be displayed if a failure occurs.*

000.002 mVDC

# Menu at a Glance

Menu is organized in a top-down tree structure with 3 levels



To turn on menu **Shift** **On/Off**


To move left or right



To move up or down



To enter command



# Math Functions

To make **null** (relative) measurement

Null

To store **min/max** readings

Min  
Max

To make **dB** measurements

Shift

dB

$dB = \text{reading in dBm} - \text{relative value in dBm}$

To make **dBm** measurements

Shift

dBm

$dBm = 10 * \text{Log}_{10} (\text{reading}^2 / \text{reference resistance} / 1mW)$

Limit testing (Access through Menu)

# Triggering

Auto-trigger: Continuously takes readings at fastest rate possible for present configuration. Default.

Single trigger: Manual trigger by pressing Single  
One reading or specified number of readings (Sample count).


Number of samples: Number of readings meter takes with each trigger: 1 to 50,000. Default is 1.

Reading hold: Select by pressing Shift Auto/Hold  
Captures and holds a stable reading on the display.

# (1) Voltage measurement

## *Principle of measurement*

A DC voltage is measured by using a voltage amplifier and an analog-to-digital converter as schematically shown in the following. A microprocessor further manipulates the data before displaying the results.



Schematic of the DMM as a DC voltage meter.

To measure a voltage, connect the nodes over which one wants to measure the voltage between the HI and LO input terminals of the DMM.

In order to activate the DMM for DC measurements you have to select the DC Voltage function by pushing the **DC V** button on the front panel.

The **Math** functions, such as Max/Min and average, can be activated (in a similar fashion as was done for the resistance measurements). Also, the range can be selected manually by pushing the **Man/Auto** key in the Range menu.

## *Errors due to the internal resistance*

An ideal voltmeter has an *infinite* input resistance so that it will not draw any current from the circuit under testing.

However, in reality, there is always a *finite* input resistance  $R_i$ . As a result, one has a voltage divider that will cause the voltage  $V_m$  one sees at the input of the voltmeter to be slightly different from the actual voltage  $V_s$  one wants to measure.

The 34401A has a relatively large input resistance of at least 10Mohm (depending on the selected voltage range) so that the error will be small as long as  $R_s \ll R_i$ .


### **CAUTION:**

**Do not exceed the maximum allowable voltage input (1000V DC).**

**Also, never apply a voltage over the current input terminal (I) of the DMM.**


# Measuring DC Voltage

1.000000 VDC




Note: measurement indicates only DC portion of signal

# Measuring DCV



- \* "Terminals" switch in "FRONT"
- \* Press **DCV**
- \* Note measurement indicates only the **dc** portion of signal



# *Range and Resolution*

<u>Range</u>	100 mV	1 V	10 V	100 V	1000 V (750 VAC)
<u>Maximum Resolution</u>	100 nV	1 $\mu$ V	10 $\mu$ V	100 $\mu$ V	1 mV (750 $\mu$ VAC)

# Resolution Choices & Integration Time

Integration Time\*\*

Resolution Choices

	.02	PLC	Fast 4 Digit	Fastest, Least Accurate
	.2	PLC	Fast 5 Digit	
	1	PLC	* Slow 4 Digit	
Default →	10	PLC	* Slow 5 Digit * Fast 6 Digit	
	100	PLC	Slow 6 Digit	


\* Equivalent to Pressing “Digits” key on front panel.

\*\*In Power Line Cycles (PLC).

Note: Integration times of .02 and .2 do not provide power-line noise rejection characteristics.


# Measuring AC Voltage

**AC to DC conversion:  
DCV proportional to AC RMS**




Note: measurement indicates only the AC portion of signal

# Measuring ACV



- \*"Terminals" switch in "FRONT"
- \* Press **ACV**
- \* Note measurement indicates only the ac portion of signal





# AC Filter

<u>Frequency</u>	<u>Range*</u>	<u>Time to settle</u>
3 Hz and above	Slow	7 sec.
20 Hz and above	Medium	1 sec.
200 Hz and above	Fast	0.1 sec.

\*Selectable through the measurement menu

# AC-Coupling vs. DC-Coupling



## AC-Coupling-Advantage



\*Removes DC Portion of Signal

---

## AC-Coupling-Disadvantage



\*Low Frequency waveforms can be cut-off

## *V<sub>rms</sub>: Root-Mean-Square*

- Instantaneous power to a resistor is:  $P = \frac{v(t)^2}{R}$
- Average power to a resistor is:

$$P_{\text{avg}} = \frac{V_{\text{rms}}^2}{R} = \frac{1}{R} \left( \frac{1}{T} \int_{t_0}^{t_0+T} v(t)^2 dt \right)$$

Solving  
for  $V_{\text{rms}}$ :

$$V_{\text{rms}} = \sqrt{\frac{1}{T} \int_{t_0}^{t_0+T} v(t)^2 dt}$$

- A given  $V_{\text{rms}}$  AC has the heating (power) effect of a VDC with the same value.

# RMS: Root-Mean-Square

\* RMS is a measure of a signal's average power. Instantaneous power delivered to a resistor is:  $P = [v(t)]^2/R$ . To get average power, integrate and divide by the period:


$$P_{avg} = \frac{1}{R} \left( \frac{1}{T} \int_{t_0}^{t_0+T} [v^2(t)] dt \right) = \frac{(V_{rms})^2}{R}$$

Solving for  $V_{rms}$ :


$$V_{rms} = \sqrt{\left( \frac{1}{T} \int_{t_0}^{t_0+T} [v^2(t)] dt \right)}$$

\* An AC voltage with a given RMS value has the same heating (power) effect as a DC voltage with that same value.


\* All the following voltage waveforms have the same RMS value, and should indicate 1.000 VAC on an rms meter:



Waveform	Sine	Triangle	Square	DC
V <sub>peak</sub>	1.414	1.733	1	1
V <sub>rms</sub>	1	1	1	1



# Peak to Peak




$$V_{rms} = V_p * .707 \text{ (Sine wave)}$$

## (2) Current measurement

### *Principle of the measurement*

An ammeter senses the current flowing through its input terminals. The ammeter (or DMM) must be connected in *series* with the circuit such the same current flows through the DMM and the test circuit.

The principle of the current measurement is quite simple. The ammeter has a small resistance  $r_i$  at its input terminals and *measures the voltage*  $V$  that the test current generates over this resistance in the following. The microprocessor then *calculates* the current,  $I=V/r_i$ , according to Ohm's law.



Principle of DC current measurement.

To use the DMM as an ammeter, one connects the leads in which the current flows to the *current* (I) and LO terminals.

To activate the ammeter, one must also select the **DC I** key by pushing **SHIFT** and DC I button.

## *Error due to the non-zero input resistance*

An ideal ammeter has a *zero* input resistance so that it does not disturb the current under test.

The *small* input resistance will cause a small voltage drop which gives a small error. Fortunately, the input resistance of the 34401A is pretty small ( $r_i = 0.1\text{ohm}$  for 1 and 3 A range, and 5 ohm for the 10mA and 100mA ranges) and can, in most cases, be ignored as long as  $R_S \gg r_i$ .

### **CAUTION:**

**Do not exceed the maximum allowable current input (3A DC).**

**Also, never apply a voltage over the current input terminal (I) of the DMM. This will cause a large current to flow through the small input resistor  $r_i$  and can damage the DMM.**

# Measuring Current


$$I = \frac{\Delta V}{r}$$

1.000000 ADC


**SHIFT** **DC I** = Measure DCI

**SHIFT** **AC I** = Measure ACI

**\* NEVER HOOK CURRENT LEADS  
DIRECTLY ACROSS A VOLTAGE SOURCE**




# Measuring CURRENT



\* **SHIFT** **DCV** = Measure DCI

\* **SHIFT** **ACV** = Measure ACI


\* Never hook current leads directly across a voltage source.




## (3) Resistance measurements

### *Principle of 2 wire measurement*

The DMM measures a resistance by applying a known DC voltage over unknown resistance in series with a small resistance  $R_m$ . It *measures the voltage* over the resistance  $R_m$  as shown in the following Figure (a). The DMM (remember the DMM has a built-in microprocessor) can then *calculate* the unknown resistance  $R$ .



(a)




(b)

Figure (a) Two-wire resistance measurement; (b) four-wire measurement.

To use the DMM for resistance measurements, connect the resistor to the terminals labeled **HI (V Ω)** and **LO**, select the resistance measurement function by pushing the **[Ω]** button (one of the function keys) on the front panel as shown below.


Notice that the selection keys are annotated in black and blue. To select the function in blue, you must first select the **blue SHIFT** key.



Function buttons to select resistance, voltage, current or frequency

# Measuring Resistance 2-wire

1.000000 k $\Omega$



\* Press  **$\Omega$  2W**

\* Resistance measured includes lead resistance

\*To eliminate the lead resistance:


- Short leads together

- Press **NULL**

- Lead resistance will be subtracted from reading

# Measuring Resistance

## Two-Wire Technique



\*"Terminals" switch in "FRONT"

\* Press **2W**

\* Since voltage is sensed at front terminals, measurement includes all lead resistance

\* To eliminate the lead resistance:

\* Short leads together

\* Press **Null**

\* Original value will now be subtracted from each reading

# Small Resistance Measurement

## *Measurement errors and NULLing function*

When one measures the value of a resistor one connects the resistor to the DMM input terminals using cables.

If the resistor one measures is very small, it is possible that the resistance of the cables themselves are comparable or even larger than the resistance of interest.

The 34401A DMM has a handy way to overcome this problem by using the NULL feature. The front panel of the DMM has a button labeled **NULL**. To null the wire resistance, one *shorts* the ends of the test wires together and then presses the NULL button. You can disable the NULL function by pushing the button again.

## *The 4-wire method*

For really accurate measurements of small resistances, there is a clever method one can use: i.e. **the 4-wire method**, as shown in the following figure.


The DMM supplies a test current through the resistor, as in the 2-wire method, but measures the voltage over the resistance with two other terminals. The two leads used for the voltage do not conduct any current, so that the *lead and contact resistances do not influence the measurement*. The **four terminals** for the **4-wire method** are shown on the front panel.

### **CAUTION:**

When doing a resistance measurements, it is **safest to disconnect all voltage sources** before connecting the DMM to the circuit. Putting a large voltage over the input terminals of the DMM may **damage the meter**.

# Measuring Resistance 4-wire

1.000000 k $\Omega$




\* Turn off "Null"

\* Press **SHIFT**  **$\Omega$ 4W**

\* No error due to lead resistance


# Measuring Resistance Four-Wire Technique



- \* Turn off "Null"
- \* "Terminals" switch in "FRONT"
- \* Press 4W
- \* Voltage is now sensed directly at the resistor, so lead resistance is not a factor

- \* Because input impedance of DC Input Amplifier is so high, no current flows through sense leads, hence no lead resistance error

# 4-Wire Resistor Measurement




$$\Delta V = I_{test} * R$$

$$R = \frac{\Delta V}{I_{test}}$$

## Range selector

The multimeter *automatically* selects the range using the auto-ranging feature.

However, you can also *manually* select a fixed range (e.g. 1KOhm or 1MOhm) using the **Auto/Man** button on the front panel (under Range/Digits) buttons. The '**down**' arrow selects the lower range and the '**up**' arrow the higher range.



Function, Math, Range and Menu keys

## *Additional features of the 34401A:*

### **average, max and min value**

One often needs to take a series of data points to find the **average** value of the measured variable. Instead of doing this by hand, the 34401A has a built-in feature that does this for us. Also, you can ask for the **maximum** and **minimum** values during the measurement interval.

To enable this feature, push the **Min/Max** button (one of the Math buttons) on the front panel. You will see the *Math* annunciator lit on the front display. Also, the DMM will make short beeps indicating it is taking readings and storing the MAX, MIN, the Average value, and the total COUNT.


Push the Min/Max button again to stop the readings.

To access these stored numbers, you have to turn the Menu on by pressing the On/Off key (**SHIFT <**) on the front panel.

Then, use the > or < keys until you are in the MATH (B) menu. You can now *go down* to the "parameter level" of the selected MIN-MAX menu by pressing the "down" button until you see the desired parameter menu (1:MIN\_MAX) displayed. Push once more the "down" button.

Once you are in the MIN-MAX menu you can use the > or < buttons to *scroll* through the menu and read the values.

The menu is organized in a top-down *tree structure* with three levels, as schematically shown in the following.



The front panel menu organization.

The MIN-MAX feature can be used for **resistance** measurements as well as for **voltage**, **current**, and **frequency** measurements.

## *Power rating of resistors*


**In addition to the value and tolerance of a resistor, the power rating is another important characteristic. It tells how much power the resistor can dissipate before being damaged by overheating. Resistors come in different power ratings: 1/8, 1/4, 1/2, 1 and 2 Watts are typical values.**

Lets look at an *example*.

Suppose you are using a 1 kohm resistor with a 0.25W power rating. The maximum DC voltage and current the resistor can tolerate is than  $V_{max}=\sqrt{P.R}=15.8V$  and  $I_{max}=\sqrt{P/R}=15.6mA$ .

**Exceeding the power rating will result in poor reliability and early break-down of the circuit. The power rating depends on the physical size of the resistor, the larger the size, the larger the power rating will be.**

# (4) Continuity Test & Diode Check




Cont = Continuity test

Shift  = Diode check

# (5) Measuring Frequency & Period


33.000,0 kHz



**Freq** = Measure Frequency

**Shift** **Period** = Measure Period


# *Frequency and Period*



$$\text{Frequency} = 1/\text{Period}$$

## (6) Ratio Measurements

DCV : DCV



$$\text{Ratio} = \frac{\text{dc signal voltage}}{\text{dc reference voltage}}$$

\*To enable ratio measurements, use the MEAS menu.

# *Voltage RMS vs. Peak*


<u>Waveform</u>	<u>Vrms</u>	<u>Vp</u>
sine	1.0	1.414
triangle	1.0	1.733
square	1.0	1.0
DC	1.0	1.0

\* Peak voltage = 1/2 of Peak to Peak voltage

# High Z Termination

SIGNAL SOURCE

MEASURING DEVICE



$$Z_c = \frac{1}{j 2\pi f C}$$

$$Z_{in} = \frac{R_i * Z_c}{R_i + Z_c}$$

High Resistance

$$V_s = \left(1 + \frac{R_o}{Z_{in}}\right) * V_m \quad \dots \text{ for very large } Z_{in}, V_s \cong V_m$$


As frequency increases,  $Z_{in}$  decreases

For less than 1% error  $Z_{in} \geq 100 R_o$

# 50 Ω Termination

SIGNAL SOURCE

MEASURING DEVICE



$$V_s = \left(1 + \frac{50\Omega}{50\Omega}\right) * V_m$$

$$V_s = 2 * V_m$$

$$V_m = \left(\frac{1}{2}\right) * V_s$$

\* $V_m$  will not equal  $V_s$ , if  $Z_{in} = R_o$ , but the ratio between them is 2:1.

- **Specifications (34401A)**

- **DC Characteristics:**

- DC Voltage range and input resistance:
  - 0.1V, 1V, 10V: input resistance selectable 10MW or > 10GW
  - 100V and 1000V:  $R_{in} = 10MW$
- DC Current range and shunt resistance:
  - 10mA, 100mA:  $R_{shunt} = 5\ W$
  - 1A and 3A: 0.1 W
- Resistance range: 2-wire and 4-wire method
  - 100 W, 1 kW, 10 kW, 100 kW, 1 MW and 100 MW
  - Input protection: 1000V

- **AC Characteristics:** true RMS

- AC Voltage: from 3 Hz to 300 kHz (for accuracy specs consult the manual)
- AC Current from 3 Hz to 5 kHz

- **Frequency and Period** measurement:

- Frequency range: 3 Hz - 300 kHz

- **Input voltage range: 100 mV to 750 V**

# Remote Interface

GP-IB (IEEE-488) Address:

Can be any value between 0 - 31. Factory set at 22.

Address 31 is talk only mode.

Adjustable only through the I/O menu.

RS-232 Interface:

Baud rate must be selected (I/O menu): 300, 600, 1200, 2400, 4800, or 9600.

Parity selection (I/O menu): Even or Odd

## Programming Languages

SCPI Language

HP 3478A Language

Fluke 8840A Language

## GP-IB




## RS-232



Not allowed

Not allowed

# Loading Errors (DC volts)




$V_s$  = ideal DUT voltage

$R_s$  = DUT source resistance

$R_i$  = multimeter input resistance  
(10 M $\Omega$  or > 10 G $\Omega$ )

$$\text{Error(\%)} = \frac{100 * R_s}{R_s + R_i}$$


# Leakage Current Errors



$I_b$  = multimeter bias current  
 $R_s$  = DUT source resistance  
 $C_i$  = multimeter input capacitance

$$\text{Error}(v) \cong I_b * R_s$$

# Common Mode Rejection (CMR)




$V_f$  = float voltage

$R_s$  = DUT source resistance  
imbalance

$R_i$  = multimeter isolation  
resistance

$$\text{Error}(v) = \frac{V_f * R_s}{R_s + R_i}$$

# Noise caused by Ground Loops




$R_I$  = lead resistance

$R_i$  = multimeter isolation resistance

$V_{ground}$  = voltage drop on ground bus


# Integrating A/D

- 1) Converts voltage to time to digits
- 2) Integrator is a line-frequency filter
- 3) Integrator is a low-pass filter



## Integrator:

$$V_{out} = -\frac{1}{C} \int_0^T i(t) dt$$



If  $R1=R2$   $\int_0^T Vx dt = \int_T^{T+To} -Vref dt$   $\Rightarrow T \cdot Vx = To \cdot (-Vref)$   $\Rightarrow \frac{Vx}{-Vref} = \frac{To}{T}$

T is fixed at one cycle of 50 Hz or 60 Hz to eliminate line noise; Vref is fixed; R, C and Time are all ratioed, so accuracy is excellent.

# ***The DIGITAL MULTIMETER***

## *Hints for Accurate Measurements:*

- ➡ Measure as near full scale as possible
- ➡ Use a Ratio measurement whenever Possible (Measure a **RATIO** rather than an absolute value) .
- ➡ Before measuring, short the test leads together to check for offsets.

(Exception: RMS AC measurements)

## *Where to get more information*

- ➡ 34401A User's Guide
- ➡ 34401A Service Guide